

Section V – Reactivity Data

Stability	Unstable		Conditions to Avoid
	Stable	X	
Incompatibility (<i>Materials to Avoid</i>) Fluorine-oxygen mixtures (that are > 50% fluorine)			
Hazardous Decomposition or Byproducts C, CO, CO ² , H ₂ O, acrolein, formaldehyde and other organic vapors.			
Hazardous Polymerization	May Occur		Conditions to Avoid None
	Will Not Occur	X	

Section VI – Health Hazard Data

Route(s) of Entry:	Inhalation? Avoid dust	Skin? Avoid hot material.	Ingestion? N/A
Health Hazards (<i>Acute and Chronic</i>) None established.			
Carcinogenicity:	NTP? N/A	IARC Monographs? N/A	OSHA Regulated? N/A
Signs and Symptoms of Exposure N/A			
Medical Conditions Generally Aggravated by Exposure N/A			
Emergency and First Aid Procedures No need anticipated.			

Section VII – Precautions for Safe Handling and Use

Steps to be Taken in Case Material is Released or Spilled Material in sheet form, restack.
Waste Disposal Method Dispose of in accordance with local regulations.
Precautions to be Taken in Handling and Storing Store away from heat sources, such as open flame.
Other Precautions Handle with good general housekeeping procedures.

Section VIII – Control Measures

Respiratory Protection (<i>Specific Type</i>) Not required.		
Ventilation	Local Exhaust Vent process equipment	Special
	Mechanical (<i>General</i>)	Other
Protective Gloves Use if material is hot or molten.	Eye Protection Safety glasses recommended.	
Other Protective Clothing or Equipment N/A		
Work/Hygienic Practices Keep away from open flame and other heated material.		

USGPO 1986-491-529/45775